

APPENDIX G

California Department of Water Resources
2009 Levee Inspection Reports for Natomas Basin

DEPARTMENT OF WATER RESOURCES

1416 NINTH STREET, P.O. BOX 942836
SACRAMENTO, CA 94236-0001
(916) 653-5791



January 26, 2010

TO: State-Federal Flood Control Project Maintaining Agencies
2009 Inspection Results

The Department of Water Resources (DWR) has completed the fall 2009 annual levee inspections for all State-Federal flood control project levees, as well as the annual project channel, structures, and pumping plant inspections. The results of your district's applicable inspections are enclosed in the following documents:

- Fall 2009 Levee Maintenance Deficiency Summary Report by Local Maintaining Agency (LMA) and by unit
- Levee Inspection Report by Mile for each unit with unit cover sheets and LMA cover sheet
- 2009 Channel Summary Report
- 2009 Structure Summary Report
- 2009 Pumping Plant Summary Report

Inspection Criteria and Ratings

A detailed explanation of all the inspection criteria can be found in the 2009 Inspection Report at <http://cdec.water.ca.gov/fsir.html>.

LMA Self-Inspections

You are again required to inspect your levee system during the December through February period. **You are only required to report any deficiencies that are different than those identified in your Fall 2009 Levee Inspection Report by Mile.** To complete your inspection report:

- Check the appropriate box on each unit cover sheet.
- Include information (location and description) as needed to identify new deficiencies.
- Sign, date, and make a copy of each sheet.
- Return the unit cover sheets and any new sheets to us by March 31, 2010.
- Please mail the reports back to DWR Summer/Winter Inspection Reports, 3310 El Camino Avenue, Room LL-30, Sacramento, California 95821-9000.

We are sending this letter and its attachments by regular mail to identified LMA officials and consultants. We are also sending this information electronically to those who have provided us with an email address. If you wish to receive such information via email instead of, or in addition to, regular mail, please inform your inspector and give him or her your email address.

If you have any questions, please contact your inspector, or contact me at (916) 574-1729 or by email at ilnewb@water.ca.gov.

Sincerely,

A handwritten signature in cursive script that reads "Ilene Wellman-Barbree".

Ilene Wellman-Barbree, Chief
Flood Project Inspection Section

Attachments

Flood Control Project Maintenance
Levee Inspections

Fall 2009 Levee Maintenance Deficiency Summary Report
Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

| RD1000 Reclamation District No. 1000 | Overall LMA Rating | Total LMA Miles | | | | |
|---|---------------------|------------------|--------------|-------------|---------------|----------|
| | A | 42.48 | | | | |
| Rated Item | M Miles | U Miles | M + 4U Miles | Threshold % | Encroachments | |
| | | | | | PO Miles | CO Miles |
| Encroachments | | | | | 11.04 | 1.31 |
| USACE Erosion Survey | 0.13 | | 0.13 | 0.31% | | |
| <i>LMA Totals:</i> | 0.13 | 0.00 | 0.13 | 0.31% | 11.04 | 1.31 |
| Unit No. 01 Sacramento River | Overall Unit Rating | Total Unit Miles | | | | |
| | A | 18.60 | | | | |
| Rated Item | M Miles | U Miles | M + 4U Miles | Threshold % | Encroachments | |
| | | | | | PO Miles | CO Miles |
| Encroachments | | | | | 7.88 | 1.31 |
| USACE Erosion Survey | 0.13 | | 0.13 | 0.70% | | |
| <i>Unit Totals:</i> | 0.13 | 0.00 | 0.13 | 0.70% | 7.88 | 1.31 |
| Unit No. 02 American River | Overall Unit Rating | Total Unit Miles | | | | |
| | A | 2.33 | | | | |
| Rated Item | M Miles | U Miles | M + 4U Miles | Threshold % | Encroachments | |
| | | | | | PO Miles | CO Miles |
| Encroachments | | | | | 2.43 | |
| <i>Unit Totals:</i> | 0.00 | 0.00 | 0.00 | 0.00% | 2.43 | 0.00 |
| Unit No. 03 Natomas East Canal | Overall Unit Rating | Total Unit Miles | | | | |
| | A | 17.17 | | | | |
| Rated Item | M Miles | U Miles | M + 4U Miles | Threshold % | Encroachments | |
| | | | | | PO Miles | CO Miles |
| Encroachments | | | | | 0.73 | |
| <i>Unit Totals:</i> | 0.00 | 0.00 | 0.00 | 0.00% | 0.73 | 0.00 |
| Unit No. 04 Natomas Cross Canal | Overall Unit Rating | Total Unit Miles | | | | |
| | A | 4.38 | | | | |
| Rated Item | M Miles | U Miles | M + 4U Miles | Threshold % | Encroachments | |
| | | | | | PO Miles | CO Miles |
| No Items | | | | | | |
| <i>Unit Totals:</i> | 0.00 | 0.00 | 0.00 | 0.00% | 0.00 | 0.00 |

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Fall 2009 Levee Inspection Results
Reclamation District No. 1000**

| | | |
|------------------------------|------|------------|
| Waterway | Bank | Unit Miles |
| Unit No. 01 Sacramento River | Left | 18.60 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | A | |
| Date of Inspection | 3/17/2009 | | 9/24/2009 | |
| DWR Inspector | Clay Thomas | | Clay Thomas | |
| Accompanied By | | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | | | |
|------------------------------|--|--|------|------------|--------------------------|-------------|
| Waterway | | | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 01 Sacramento River | | | Left | 18.60 | 11/24/2009 12/01/2009 | Clay Thomas |

| LMR No. | Levee Mile | | Category | Item | * Location | ** Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|--------------------|----------------------|------------|-------------|---|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.08 | 0.08 | Earthen Levee | Encroachments | WS PO | Buildings | | 38.779583 ° -121.602598 ° | 38.779583 ° -121.602598 ° | 957 |
| 2 | 0.18 | 0.22 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.778408 ° -121.601488 ° | 38.777902 ° -121.601062 ° | 131 |
| 3 | 0.48 | 0.61 | Supplemental Levee | USACE Erosion Survey | WS M | | Inspector Comments: tree hazards, seepage | 38.774507 ° -121.598865 ° | 38.772921 ° -121.597788 ° | 953 |
| 4 | 1.69 | 1.71 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.758697 ° -121.591178 ° | 38.758447 ° -121.591253 ° | 136 |
| 5 | 1.74 | 1.77 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.757962 ° -121.591342 ° | 38.757480 ° -121.591147 ° | 135 |
| 6 | 1.77 | 1.79 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.757478 ° -121.591140 ° | 38.757238 ° -121.591272 ° | 134 |
| 7 | 1.88 | 1.91 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.755975 ° -121.591433 ° | 38.755585 ° -121.591530 ° | 133 |
| 8 | 1.96 | 1.98 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.754848 ° -121.591742 ° | 38.754562 ° -121.591795 ° | 132 |
| 9 | 2.02 | 2.03 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.753983 ° -121.591737 ° | 38.753848 ° -121.591797 ° | 129 |
| 10 | 2.04 | 2.04 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.753691 ° -121.592149 ° | 38.753691 ° -121.592149 ° | 123 |
| 11 | 2.11 | 2.18 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.752513 ° -121.592017 ° | 38.751822 ° -121.592857 ° | 122 |
| 12 | 2.55 | 2.70 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.747087 ° -121.595582 ° | 38.745127 ° -121.596793 ° | 121 |
| 13 | 5.23 | 5.29 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.711248 ° -121.610500 ° | 38.710700 ° -121.611233 ° | 120 |
| 14 | 5.31 | 5.34 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.710508 ° -121.611450 ° | 38.710132 ° -121.611882 ° | 119 |
| 15 | 5.55 | 5.55 | Earthen Levee | Rip Rap Revelments | WS C | | Inspector Comments: erosion repair site | 38.708156 ° -121.614518 ° | 38.708156 ° -121.614518 ° | 958 |
| 16 | 5.68 | 5.72 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.706593 ° -121.616155 ° | 38.706082 ° -121.616385 ° | 118 |
| 17 | 5.72 | 5.75 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.706085 ° -121.616385 ° | 38.705662 ° -121.616837 ° | 117 |
| 18 | 6.04 | 6.07 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.702742 ° -121.620557 ° | 38.702467 ° -121.620947 ° | 116 |

| | | | |
|--|--|--|---------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected |
|--|--|--|---------------|

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | | |
|------------------------------|--|------|------------|--------------------------|-------------|
| Waterway | | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 01 Sacramento River | | Left | 18.60 | 11/24/2009 12/01/2009 | Clay Thomas |

| LMR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|---------------|----------|-------------|----------------|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 19 | 6.20 | 6.22 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.701422 ° -121.622755 ° | 38.701120 ° -121.623063 ° | 113 |
| 20 | 6.22 | 6.24 | Earthen Levee | Encroachments | LS PO | Landscaping | | 38.701177 ° -121.623057 ° | 38.700950 ° -121.623375 ° | 115 |
| 21 | 6.22 | 6.24 | Earthen Levee | Encroachments | LS PO | Fences | | 38.701178 ° -121.623060 ° | 38.700947 ° -121.623370 ° | 114 |
| 22 | 6.22 | 6.25 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.701120 ° -121.623065 ° | 38.700822 ° -121.623468 ° | 112 |
| 23 | 6.36 | 6.39 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.699877 ° -121.624948 ° | 38.699575 ° -121.625475 ° | 111 |
| 24 | 6.41 | 6.47 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.756757 ° -121.596252 ° | 38.757943 ° -121.599515 ° | 124 |
| 25 | 6.43 | 6.47 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.699237 ° -121.626088 ° | 38.698907 ° -121.626617 ° | 110 |
| 26 | 6.49 | 6.49 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.758607 ° -121.601933 ° | 38.758607 ° -121.601933 ° | 125 |
| 27 | 6.58 | 6.61 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.697958 ° -121.628273 ° | 38.697773 ° -121.628682 ° | 109 |
| 28 | 6.61 | 6.70 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.697775 ° -121.628685 ° | 38.696618 ° -121.629425 ° | 108 |
| 29 | 6.76 | 6.78 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.695892 ° -121.630053 ° | 38.695642 ° -121.630353 ° | 107 |
| 30 | 6.88 | 6.89 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.694348 ° -121.631007 ° | 38.694187 ° -121.631200 ° | 106 |
| 31 | 6.89 | 6.92 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.694192 ° -121.631203 ° | 38.693932 ° -121.631470 ° | 105 |
| 32 | 6.92 | 6.95 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.693935 ° -121.631478 ° | 38.693412 ° -121.631765 ° | 104 |
| 33 | 6.99 | 7.03 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.693043 ° -121.632048 ° | 38.692553 ° -121.632373 ° | 103 |
| 34 | 7.03 | 7.07 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.692535 ° -121.632423 ° | 38.691872 ° -121.632490 ° | 102 |
| 35 | 7.10 | 7.16 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.691422 ° -121.632585 ° | 38.690707 ° -121.632842 ° | 101 |
| 36 | 7.16 | 7.18 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.690678 ° -121.632840 ° | 38.690367 ° -121.632797 ° | 100 |

| | | | |
|--|--|--|---------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected |
|--|--|--|---------------|

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | | | |
|------------------------------|--|--|------|------------|--------------------------|-------------|
| Waterway | | | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 01 Sacramento River | | | Left | 18.60 | 11/24/2009 12/01/2009 | Clay Thomas |

| Levee No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|-----------|------------|------|---------------|---------------|----------|-------------|----------------|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 37 | 7.22 | 7.27 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.689753 ° -121.632788 ° | 38.689077 ° -121.633003 ° | 99 |
| 38 | 7.36 | 7.36 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.687808 ° -121.632495 ° | 38.687808 ° -121.632495 ° | 97 |
| 39 | 7.36 | 7.36 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.687808 ° -121.632495 ° | 38.687808 ° -121.632495 ° | 98 |
| 40 | 7.39 | 7.43 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.687347 ° -121.632433 ° | 38.686780 ° -121.632138 ° | 96 |
| 41 | 7.66 | 7.72 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.683620 ° -121.631180 ° | 38.682742 ° -121.631190 ° | 95 |
| 42 | 7.72 | 7.75 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.682742 ° -121.631168 ° | 38.682310 ° -121.631085 ° | 94 |
| 43 | 7.81 | 7.86 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.681592 ° -121.630768 ° | 38.680837 ° -121.630530 ° | 93 |
| 44 | 8.08 | 8.11 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.678023 ° -121.628670 ° | 38.677672 ° -121.628432 ° | 92 |
| 45 | 8.18 | 8.19 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.676893 ° -121.627860 ° | 38.676747 ° -121.627725 ° | 91 |
| 46 | 8.22 | 8.25 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.676425 ° -121.627462 ° | 38.676038 ° -121.627063 ° | 90 |
| 47 | 8.25 | 8.28 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.676040 ° -121.627063 ° | 38.675772 ° -121.626785 ° | 89 |
| 48 | 8.36 | 8.38 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.674830 ° -121.625830 ° | 38.674610 ° -121.625652 ° | 88 |
| 49 | 8.38 | 8.42 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.674607 ° -121.625655 ° | 38.674117 ° -121.625143 ° | 87 |
| 50 | 8.56 | 8.59 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.672878 ° -121.623203 ° | 38.672603 ° -121.622892 ° | 86 |
| 51 | 8.60 | 8.66 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.672487 ° -121.622783 ° | 38.671790 ° -121.622118 ° | 85 |
| 52 | 8.77 | 8.86 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.670647 ° -121.620632 ° | 38.669790 ° -121.619482 ° | 84 |
| 53 | 8.96 | 8.98 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.668898 ° -121.618195 ° | 38.668672 ° -121.617775 ° | 83 |
| 54 | 8.98 | 9.02 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.668673 ° -121.617772 ° | 38.668405 ° -121.617278 ° | 82 |

| | | | |
|--|--|--|---------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected |
|--|--|--|---------------|

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | |
|------------------------------|------|------------|--------------------------|-------------|
| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 01 Sacramento River | Left | 18.60 | 11/24/2009 12/01/2009 | Clay Thomas |

| LIR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|-------|---------------|----------------|----------|--|----------------|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 55 | 9.03 | 9.08 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.668312 ° -121.617138 ° | 38.667783 ° -121.616382 ° | 81 |
| 56 | 9.09 | 9.11 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.667672 ° -121.616215 ° | 38.667552 ° -121.616018 ° | 80 |
| 57 | 9.11 | 9.14 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.667505 ° -121.615912 ° | 38.667255 ° -121.615525 ° | 79 |
| 58 | 9.15 | 9.17 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.667250 ° -121.615522 ° | 38.667028 ° -121.615115 ° | 78 |
| 59 | 9.57 | 9.57 | Earthen Levee | Encroachments | WS CO | Buildings | | 38.663307 ° -121.609949 ° | 38.663307 ° -121.609949 ° | 959 |
| 60 | 10.28 | 10.28 | Earthen Levee | Animal Control | WS C | Exterminate rodents and backfill and compact or grout burrows. | | 38.655161 ° -121.601900 ° | 38.655161 ° -121.601900 ° | 954 |
| 61 | 10.34 | 10.36 | Earthen Levee | Encroachments | LS PO | Landscaping | | 38.654508 ° -121.601280 ° | 38.654332 ° -121.601097 ° | 75 |
| 62 | 10.88 | 10.92 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.648127 ° -121.595872 ° | 38.647663 ° -121.595483 ° | 74 |
| 63 | 10.95 | 10.99 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.647373 ° -121.595248 ° | 38.646825 ° -121.594800 ° | 73 |
| 64 | 11.23 | 11.30 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.644548 ° -121.591768 ° | 38.644302 ° -121.590572 ° | 72 |
| 65 | 11.42 | 11.51 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.644393 ° -121.588498 ° | 38.644702 ° -121.586992 ° | 70 |
| 66 | 11.62 | 11.62 | Earthen Levee | Animal Control | WS C | Exterminate rodents and backfill and compact or grout burrows. | | 38.645479 ° -121.585212 ° | 38.645479 ° -121.585212 ° | 955 |
| 67 | 11.84 | 11.88 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.647408 ° -121.582090 ° | 38.647773 ° -121.581423 ° | 69 |
| 68 | 12.21 | 12.24 | Earthen Levee | Encroachments | LS PO | Landscaping | | 38.650302 ° -121.576493 ° | 38.650216 ° -121.575890 ° | 63 |
| 69 | 12.25 | 12.29 | Earthen Levee | Encroachments | LS CO | Buildings | | 38.650315 ° -121.575622 ° | 38.650367 ° -121.575005 ° | 68 |
| 70 | 12.33 | 12.35 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.653208 ° -121.573895 ° | 38.650245 ° -121.572188 ° | 66 |
| 71 | 12.35 | 12.43 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.650867 ° -121.573877 ° | 38.648223 ° -121.569630 ° | 67 |
| 72 | 12.44 | 12.55 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.651785 ° -121.571670 ° | 38.649560 ° -121.570438 ° | 65 |

| | |
|--|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected |
|--|---|

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | |
|------------------------------|------|------------|--------------------------|-------------|
| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 01 Sacramento River | Left | 18.60 | 11/24/2009 12/01/2009 | Clay Thomas |

| LMR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|-------|---------------|---------------|----------|---|----------------|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 73 | 12.55 | 12.59 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.649533 ° -121.570387 ° | 38.649253 ° -121.569810 ° | 64 |
| 74 | 12.59 | 12.64 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.649253 ° -121.569815 ° | 38.648895 ° -121.569043 ° | 62 |
| 75 | 12.64 | 12.67 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.648897 ° -121.569030 ° | 38.648588 ° -121.568467 ° | 61 |
| 76 | 12.72 | 12.77 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.648172 ° -121.567843 ° | 38.647738 ° -121.567167 ° | 60 |
| 77 | 12.77 | 12.85 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.647665 ° -121.567045 ° | 38.646812 ° -121.566135 ° | 59 |
| 78 | 12.89 | 12.98 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.646400 ° -121.565695 ° | 38.645302 ° -121.564733 ° | 58 |
| 79 | 13.08 | 13.08 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.644028 ° -121.563823 ° | 38.644028 ° -121.563823 ° | 56 |
| 80 | 13.12 | 13.13 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.643527 ° -121.563518 ° | 38.643378 ° -121.563402 ° | 55 |
| 81 | 13.13 | 13.14 | Earthen Levee | Encroachments | WS PO | Fences | | 38.643380 ° -121.563400 ° | 38.643275 ° -121.563307 ° | 54 |
| 82 | 13.26 | 13.30 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.641620 ° -121.562753 ° | 38.641113 ° -121.562557 ° | 52 |
| 83 | 13.27 | 14.57 | Earthen Levee | Vegetation | LS C | Remove the wild growth other than native grasses from the levee slopes. | | 38.640471 ° -121.562497 ° | 38.623167 ° -121.560322 ° | 137 |
| 84 | 13.34 | 17.63 | Earthen Levee | Encroachments | LS PO | Agricultural Ditch | | 38.640469 ° -121.562502 ° | 38.605560 ° -121.528054 ° | 956 |
| 85 | 13.36 | 13.41 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.640205 ° -121.562370 ° | 38.639540 ° -121.562238 ° | 51 |
| 86 | 13.47 | 13.51 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.638668 ° -121.562085 ° | 38.638065 ° -121.562015 ° | 50 |
| 87 | 13.51 | 13.55 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.638067 ° -121.562013 ° | 38.637600 ° -121.561932 ° | 49 |
| 88 | 13.55 | 13.58 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.637602 ° -121.561930 ° | 38.637060 ° -121.561833 ° | 48 |
| 89 | 13.58 | 13.62 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.637052 ° -121.561833 ° | 38.636527 ° -121.561743 ° | 47 |
| 90 | 13.60 | 13.60 | Earthen Levee | Encroachments | LS PO | Landscaping | | 38.636842 ° -121.561804 ° | 38.636842 ° -121.561804 ° | 138 |

| | |
|--|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected |
|--|---|

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| Waterway | | | | Bank | Unit Miles | Inspection Start/End | Inspector | | | |
|------------------------------|------------|-------|---------------|---------------|------------|--------------------------|----------------|------------------------------|------------------------------|-----------------|
| Unit No. 01 Sacramento River | | | | Left | 18.60 | 11/24/2009 12/01/2009 | Clay Thomas | | | |
| LWR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
| | Start | End | | | | | | Start | End | |
| 91 | 13.62 | 13.64 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.636522 ° -121.561743 ° | 38.636250 ° -121.561667 ° | 46 |
| 92 | 13.68 | 13.70 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.635638 ° -121.561570 ° | 38.635387 ° -121.561497 ° | 45 |
| 93 | 13.70 | 13.72 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.635390 ° -121.561490 ° | 38.635032 ° -121.561482 ° | 44 |
| 94 | 13.86 | 13.90 | Earthen Levee | Encroachments | WS CO | Fences | | 38.633238 ° -121.561097 ° | 38.632590 ° -121.560915 ° | 43 |
| 95 | 14.21 | 14.24 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.628300 ° -121.560180 ° | 38.627873 ° -121.560202 ° | 42 |
| 96 | 14.31 | 14.32 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.626905 ° -121.560062 ° | 38.626863 ° -121.561015 ° | 41 |
| 97 | 14.37 | 14.39 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.625975 ° -121.560127 ° | 38.625642 ° -121.560185 ° | 39 |
| 98 | 14.38 | 14.52 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.623976 ° -121.560372 ° | 38.623812 ° -121.561345 ° | 40 |
| 99 | 14.79 | 14.82 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.620077 ° -121.560120 ° | 38.619630 ° -121.560067 ° | 38 |
| 100 | 14.85 | 14.90 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.619112 ° -121.560113 ° | 38.618493 ° -121.560070 ° | 37 |
| 101 | 14.92 | 14.92 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.618163 ° -121.560113 ° | 38.618163 ° -121.560113 ° | 36 |
| 102 | 14.98 | 15.02 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.617388 ° -121.559970 ° | 38.616835 ° -121.559807 ° | 35 |
| 103 | 15.33 | 15.38 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.612555 ° -121.558258 ° | 38.611900 ° -121.558303 ° | 34 |
| 104 | 15.46 | 15.48 | Earthen Levee | Encroachments | WS PO | Fences | | 38.610787 ° -121.557817 ° | 38.610455 ° -121.557638 ° | 33 |
| 105 | 15.50 | 15.52 | Earthen Levee | Encroachments | WS PO | Fences | | 38.610180 ° -121.557453 ° | 38.609908 ° -121.557328 ° | 32 |
| 106 | 15.54 | 15.57 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.609743 ° -121.557252 ° | 38.609315 ° -121.557000 ° | 31 |
| 107 | 15.70 | 15.73 | Earthen Levee | Encroachments | WS CO | Landscaping | | 38.607715 ° -121.555847 ° | 38.607345 ° -121.555538 ° | 30 |
| 108 | 15.74 | 15.82 | Earthen Levee | Encroachments | WS CO | Fences | | 38.607207 ° -121.555465 ° | 38.606255 ° -121.554582 ° | 29 |

| | |
|--|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected |
|--|---|

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | | |
|------------------------------|--|------|------------|--------------------------|-------------|
| Waterway | | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 01 Sacramento River | | Left | 18.60 | 11/24/2009 12/01/2009 | Clay Thomas |

| LMR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|-------|---------------|---------------|----------|-------------|----------------|------------------------------|------------------------------|-----------------|
| | Start | End | | | | | | Start | End | |
| 109 | 15.85 | 15.87 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.605915 ° -121.554290 ° | 38.605687 ° -121.554070 ° | 28 |
| 110 | 15.88 | 15.91 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.605585 ° -121.553983 ° | 38.605273 ° -121.553663 ° | 27 |
| 111 | 15.91 | 15.93 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.605265 ° -121.553647 ° | 38.605032 ° -121.553437 ° | 26 |
| 112 | 15.93 | 15.97 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.605002 ° -121.553413 ° | 38.604598 ° -121.553008 ° | 25 |
| 113 | 16.09 | 16.10 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.603083 ° -121.551690 ° | 38.602943 ° -121.551593 ° | 23 |
| 114 | 16.11 | 16.13 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.602870 ° -121.551598 ° | 38.602617 ° -121.551330 ° | 22 |
| 115 | 16.14 | 16.16 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.602517 ° -121.551248 ° | 38.602373 ° -121.550963 ° | 21 |
| 116 | 16.20 | 16.23 | Earthen Levee | Encroachments | WS PO | Fences | | 38.601977 ° -121.550473 ° | 38.601678 ° -121.550142 ° | 20 |
| 117 | 16.30 | 16.33 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.600988 ° -121.549198 ° | 38.600665 ° -121.548795 ° | 19 |
| 118 | 16.34 | 16.36 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.600525 ° -121.548640 ° | 38.600397 ° -121.548447 ° | 18 |
| 119 | 16.86 | 16.90 | Earthen Levee | Encroachments | WS CO | Fences | | 38.602328 ° -121.540788 ° | 38.602688 ° -121.540157 ° | 16 |
| 120 | 16.90 | 16.95 | Earthen Levee | Encroachments | WS PO | Fences | | 38.602693 ° -121.540165 ° | 38.603092 ° -121.539490 ° | 15 |
| 121 | 16.97 | 17.00 | Earthen Levee | Encroachments | WS PO | Fences | | 38.603242 ° -121.539318 ° | 38.603597 ° -121.538875 ° | 14 |
| 122 | 17.06 | 17.18 | Earthen Levee | Encroachments | WS PO | Fences | | 38.604188 ° -121.538027 ° | 38.604890 ° -121.536105 ° | 13 |
| 123 | 17.64 | 17.74 | Earthen Levee | Encroachments | WS PO | Fences | | 38.605645 ° -121.527902 ° | 38.605542 ° -121.526112 ° | 11 |
| 124 | 17.77 | 17.82 | Earthen Levee | Encroachments | WS CO | Buildings | | 38.605482 ° -121.525492 ° | 38.605447 ° -121.524678 ° | 10 |
| 125 | 17.82 | 17.91 | Earthen Levee | Encroachments | WS CO | Buildings | | 38.605445 ° -121.524675 ° | 38.605305 ° -121.522958 ° | 8 |
| 126 | 17.83 | 17.86 | Earthen Levee | Encroachments | LS CO | Buildings | | 38.605420 ° -121.524375 ° | 38.605462 ° -121.523852 ° | 9 |

| | | | |
|--|--|---|----------------------|
| <p>* Location</p> <p>LS : Land Side</p> <p>WS : Water Side</p> <p>CR : Crown</p> | <p>** Rating</p> <p>A : Acceptable</p> <p>M : Minimally Acceptable</p> <p>U : Unacceptable</p> | <p>PO : Partially Obstructing</p> <p>CO : Completely Obstructing</p> <p>N : Not Inspected</p> | <p>C : Corrected</p> |
|--|--|---|----------------------|

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | | |
|------------------------------|--|------|------------|--------------------------|-------------|
| Waterway | | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 01 Sacramento River | | Left | 18.60 | 11/24/2009 12/01/2009 | Clay Thomas |

| LMI/UNIT No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|--------------|------------|-------|---------------|---------------|----------|-----------|----------------|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 127 | 17.91 | 17.94 | Earthen Levee | Encroachments | WS CO | Buildings | | 38.605300 ° -121.522957 ° | 38.605200 ° -121.522422 ° | 7 |
| 128 | 18.10 | 18.10 | Earthen Levee | Encroachments | WS CO | Buildings | | 38.604788 ° -121.519720 ° | 38.604788 ° -121.519720 ° | 6 |
| 129 | 18.10 | 18.18 | Earthen Levee | Encroachments | WS CO | Buildings | | 38.604758 ° -121.519610 ° | 38.604532 ° -121.518190 ° | 5 |
| 130 | 18.21 | 18.40 | Earthen Levee | Encroachments | WS CO | Buildings | | 38.604515 ° -121.517635 ° | 38.603918 ° -121.514370 ° | 4 |

| | |
|--|---|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected |
|--|---|

Flood Control Project Maintenance
Levee Inspections

Unit Cover Sheet

Fall 2009 Levee Inspection Results

Reclamation District No. 1000

| | | |
|----------------------------|-------|------------|
| Waterway | Bank | Unit Miles |
| Unit No. 02 American River | Right | 2.33 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | A | |
| Date of Inspection | 3/17/2009 | | 9/24/2009 | |
| DWR Inspector | Clay Thomas | | Clay Thomas | |
| Accompanied By | | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | | |
|----------------------------|--|-------|------------|--------------------------|-------------|
| Waterway | | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 02 American River | | Right | 2.33 | 12/01/2009 12/01/2009 | Clay Thomas |

| LIR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|------|---------------|---------------|----------|-------------|----------------|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.07 | 2.30 | Earthen Levee | Encroachments | LS PO | Landscaping | | 38.604932 ° -121.510243 ° | 38.605932 ° -121.470770 ° | 1 |
| 2 | 1.50 | 1.70 | Earthen Levee | Encroachments | WS PO | Landscaping | | 38.607880 ° -121.484500 ° | 38.607110 ° -121.480950 ° | 2 |

| | | | |
|--|--|--|---------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected |
|--|--|--|---------------|

Flood Control Project Maintenance
Levee Inspections

Unit Cover Sheet

Fall 2009 Levee Inspection Results

Reclamation District No. 1000

| | | |
|--------------------------------|-------|------------|
| Waterway | Bank | Unit Miles |
| Unit No. 03 Natomas East Canal | Right | 17.17 |

| | Spring (March - May) | Summer (June - August) | (September - November) Fall | Winter (December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit Maintenance Rating (Fall Only) | | | A | |
| Date of Inspection | 3/17/2009 | | 9/24/2009 | |
| DWR Inspector | Clay Thomas | | Clay Thomas | |
| Accompanied By | | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item Identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | |
|--------------------------------|-------|------------|--------------------------|-------------|
| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 03 Natomas East Canal | Right | 17.17 | 11/24/2009 12/01/2009 | Clay Thomas |

| LMR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. Photo |
|---------|------------|-------|---------------|---------------|----------|--------------------|----------------|------------------------------|------------------------------|--------------------|
| | Start | End | | | | | | Start | End | |
| 1 | 0.07 | 0.13 | Earthen Levee | Encroachments | LS PO | Fences | | 38.606882 ° -121.469480 ° | 38.607523 ° -121.469033 ° | 7 |
| 2 | 0.30 | 0.32 | Earthen Levee | Encroachments | LS PO | Fences | | 38.609865 ° -121.468183 ° | 38.610162 ° -121.468122 ° | 5 |
| 3 | 0.53 | 0.57 | Earthen Levee | Encroachments | LS PO | Fences | | 38.613077 ° -121.468133 ° | 38.613700 ° -121.468263 ° | 4 |
| 4 | 3.05 | 3.10 | Earthen Levee | Encroachments | LS PO | Fences | | 38.648677 ° -121.474882 ° | 38.649412 ° -121.475005 ° | 3 |
| 5 | 14.54 | 14.94 | Earthen Levee | Encroachments | LS C | Agricultural Ditch | | 38.804665 ° -121.516013 ° | 38.809031 ° -121.518615 ° | 8 |
| 6 | 15.51 | 16.07 | Earthen Levee | Encroachments | LS PO | Agricultural Ditch | | 38.816259 ° -121.522787 ° | 38.823314 ° -121.526942 ° | 9 |

| | | | |
|--|--|--|---------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected |
|--|--|--|---------------|

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2009 Levee Inspection Results

Reclamation District No. 1000

| | | | |
|--|-------------------------|---------------------------|--------------------------------|
| Waterway | | Bank | Unit Miles |
| Unit No. 04 Natomas Cross Canal | | Left | 4.38 |
| | Spring (March - May) | Summer (June - August) | (September - November) Fall |
| Unit Maintenance Rating (Fall Only) | | | A |
| Date of Inspection | | | 9/24/2009 |
| DWR Inspector | | | Clay Thomas |
| Accompanied By | | | |

Check one:

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item Identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

Flood Control Project Maintenance
Levee Inspections

Levee Inspection Report By Mile - Fall 2009

Reclamation District No. 1000

| | | | | |
|---------------------------------|------|------------|--------------------------|-------------|
| Waterway | Bank | Unit Miles | Inspection Start/End | Inspector |
| Unit No. 04 Natomas Cross Canal | Left | 4.38 | 11/24/2009 11/24/2009 | Clay Thomas |

| LMR No. | Levee Mile | | Category | Item | Location | Rating | Action/Comment | GPS Latitude/Longitude | | Issue No. |
|---------|------------|-----|----------|------|----------|--------|--------------------------|------------------------|-----|-----------|
| | Start | End | | | | | | Start | End | Photo |
| 1 | | | | | | | No issues were reported. | | | |

| | | | |
|--|--|--|---------------|
| * Location LS : Land Side WS : Water Side CR : Crown | ** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable | PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected | C : Corrected |
|--|--|--|---------------|